

**It is strongly recommended that you upgrade the software in all your cabinets to the most current versions.
Any versions not listed are obsolete and must be upgraded.**

Winning Touch 1.0

<u>USB Drive Label</u>	<u>Logic Box</u>	<u>Intralot Version ID</u>
BNDL55H0141	4.1	468 or WinningTouch_10_BNDL55H0141
BNDL55H0141	4.1V2	469 or WinningTouch_10_BNDL55H0141v2